

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0563/1

Work Order Type: Weatherization

Audit Name: 80008KN0563-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0563

Alt. Client ID: Knox

<u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1940

An EPA Certified Firm/Renovator is required.

i	Measure		Wind E2 E3	ow Glazing (7) (N1 N2 i)	W1 W2 S	1	Componen	ts			Inspected
С		Nev	v glazi	glazing must be 100% r ing should be even, sm ards for Weatherization	ooth, and	all look	uniform. Re	efer to Ar	nendix	<	
						-	Estimated	!		Actual	
#	Material /	Labo	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecif	ied	,	Window Glazing (+)	Each	7					
2	Labor		ł	abor	Each	7					
0	ther Detail	1									
L											
											-
					ı	Measure	Sub Total:	-		Sub Total:	
	Field Note	s:	, Tan						No.		

Report Run On: 5/6/2010

Measure 2 DV	WH Pipe Insulation			Componen	ts	***		Inspected
Comment					· ·			
				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
					77			
		ı	Measur	e Sub Total:			Sub Total:	
Fleld Notes:				7/11	-/	1100-	L	
								:
	No.							-

Tank Insulation			Componen	ts			Inspected
ressure relief pipe as ne	eded.		-				
			Estimated	1		Actual	 1
Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
DHW Tank Insulation	Each	1					
minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast							L
DHW Tank Insulation	Each	1					
							_
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
		Measur	e Sub Total:		S	Sub Total:	
							J
	ressure relief pipe as ne	Description / Comment Units DHW Tank Insulation Each Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. DHW Tank Insulation Each	Description / Comment Units Qty DHW Tank Insulation Each 1 Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. DHW Tank Insulation Each 1	Description / Comment Units Qty Unit Cost DHW Tank Insulation Each 1 Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.	Pescription / Comment Units Qty Unit Cost Total DHW Tank Insulation Each 1 Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. DHW Tank Insulation Each 1	ressure relief pipe as needed. Description / Comment Units Qty Unit Cost Total Qty	ressure relief pipe as needed. Estimated Actual

Report Run On: 5/6/2010

Measure 4	1 Floor	Ins. R-19			Componen	ts F1			Inspected
k 9 9 (pefore ins Standards subfloor a e.g. stave compress	labor cost. Contractor's talling insulation. Cont is. Insulation is installed bove (paper side againes for blankets). Insulations. Refer to Appendicast Field Guide.	ractor to in d to mainta nst subfloo ation to hav	stall u in per r) inclu e NO	sing Resnet manent cont uding necess gaps, voids,	Grade 1 act with t sary supp or	he orts		
_					Estimated			Actual	
# Material / L	abor i	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	-	Floor Insulation <i>-</i> Fiberglass Batts - R-19	SqFt	675				***************************************	
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	675					
Other Detail									
						777			
			ħ	Measur	e Sub Total:		S	Sub Total:	
Field Notes.	•								

Report Run On: 5/6/2010

	Measure	5 Stor	m Windows			Componen	ts S1,W2	,N1,E	3	Inspected
C	Comment	measure before o	s labor and material. Reference. Responsibility of ordering window(s). Contract and any other related ite	contract actor to i	or to ve nclude	ram for esting if the sting if the state of	mated ments in t break, cau neasure.	he fiel		
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	;	Storm Window	Each	4					70.07
			Includes labor and material. Refer to House diagram for estimated measurements. Responsibility of contractor to verify measurements in the field before ordering window(s). Contractor must follow all egress codes if applicable. Contractor to include the thermal break, caulking, framing, and any other related items to convey a completed measure.							
2	Labor		Storm Window	Each	4					
o	ther Detail					· · · · · · · · · · · · · · · · · · ·				
L.	······································									
	,									
					Measure	Sub Total:			ub Total:	
	Field Notes	>:			<u></u>					

	<i>Measure</i> 6 Sma	rt Thermostat		····	Componen	ts	· · · · · · · · · · · · · · · · · · ·		Inspected
C	I hermos	ermostat. Must be equal stat (must submit equival client on operation of the	ent to Ho	using [PRO 4000 P Director for a	rogramm pproval)	able . Must		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipmen	Smart Thermostat	Each	1					
		Includes labor cost. Must be equal to Honeywell's PRO 4000 Programmable Thermostat. Must be installed by a qualified technician. Must train homeowner on operation of thermostat. Refer to Appendix A- Standards for Weatherization Materials and South East Field Guide.							
2	Labor	Smart Thermostat	Each	1		7.11			
0	ther Detail						1		
					C 7-4-1-		الـــــا		
Г	FI-1-1AL (weasure	Sub Fotal:			ub rotai:	
	Field Notes:			Measure	Sub Total:	-	<i>S</i>	ub Total:	

Client ID: 80008KN0563
Alt. Client ID: Knox

Measure 7 CO	Monitor is Needed			Componen	ts			Inspecte
Comment Refer to Field G	o Attachment A- Standard uide.	ds for Wea	theriz			utheas	st	
				Estimated	! 		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety 	CO monitor	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.				•			
2 Labor	Labor	Each	1					
Other Detail								***
					,,,,,			
			Measur	e Sub Total:			Sub Total:	
(Bas Comment Must be walls an earth. M	or Barrier Needed ement/CrawIspace)(531 6 mil poly. Must be instal d support piers. Must be ust be secured at all sear ization Materials and Soc	lled 100% securely f ms. Refer	of crav astene to Atta	ed. Must be o schment A- S	6" turned	wn to		Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	531					
2 Labor	Labor	SqFt	531					Timila
Other Detail								
			easure	Sub Total:		S:	ub Total:	
Field Notes:	1704					704	·	
								-
				****			, au	

Client Name:

Alt. Client ID: Knox

Client ID: 80008KN0563

Work Order (Bid Form)

Work Order Name: WO/80008KN0563/1 Report Run On: 5/6/2010 DOE Weatherization Assistant Version 8.6.0

Page 8 of 9

Work Order Grand Total: Grand Total:

Page 9 of 9